

SERVICE WORK RATE SCHEDULE

2024-2025

(Prices are subject to change without notice)

Winter Storage Program, inside boat storage Waste tank must be pumped prior to arrival at Lanes End.

Jet Ski delivered to Lanes End on trailer or to docks

Labor Rate Per Hour

Service Call to Customer's Location

\$62 per linear foot of boat

(see web page for list of included services)

Single PWC \$650, Two on Tandem Trailer, \$1100

\$175 + parts and additional labor

Winterize Engine (One engine included in Winter Storage Program)

Gear Oil change (Required when storing, usually just I/O and O/B motors)

Transmission Fluid Change—Inboards only (Recommended Every Two Years)

Change Engine Oil & Filter (Lube, oil, filter) (Recommended Every Two Years)

Change Water-Separating Fuel Filter (Recommended with every Engine Oil change)

Pick up Boat from your location for Storage

Wash Bottom & Sides from the rub rail down-Acid (storage boats)

Wash Pontoons-Detergent (storage boats)

Wash Entire Hull Exterior-Acid or Detergent (storage boats)

Propeller Reconditioning (Required if damaged)

Oil-Absorbent Bilge Sock to Reduce Lake Pollutants

\$165

\$165

\$165

Winterization of Fresh Water System (live well, ballast, washdown, sink, toilet)

Single Prop: \$95 plus materials and disposal fees Dual Prop: \$120 plus materials and disposal fees

\$80 plus materials and disposal fees

\$100 plus oil, filter and disposal fee O/B \$50 +

\$15 or \$35 plus filter

\$165 per hour per technician needed

\$13 per foot; Tritoon is \$17 per foot

\$17 per foot

Price based on size and type of propeller

\$10.00 no charge for labor

Winter Work

Wax Bottom and Sides-Requires wash bottom & sides in Fall

Wax Entire Boat-Requires wash bottom & sides in Fall

Boats with fiberglass interior will incur an additional \$50 flat fee

Canvas Cleaning

Canvas / Upholstery Repair or Replacement

Fiberglass Repair, Gel Coat Repair, Repainting Outdrive

\$17 per foot

Boats 22' and less: \$19 per foot; Boats 23' and longer is

\$21 per foot

\$165 per hour

Email or Call to request a Quote

\$165 per hour

Spring Services

De-Winterize Engine (one engine included in Winter Storage Pro-

De-Winterization of Fresh Water System

Spark, Plugs Remove & Replace (O/B and jet tune-up)

Tune-Up Engine for I/O, I/B (includes changing spark plugs)

I/O Combo Service: Water Pump Service & Outdrive Service

Water Pump Service (Rec. Every 2 years for I/O; every 3-4 years for O/B)

Outdrive Service Remove and Inspect

Battery, Remove & Replace

Deliver boat or jet ski to your location

I/O & I/B—\$165 O/B—\$125 |et Ski—\$165

\$165

\$185 to \$325 plus parts

O/B & Jet Ski \$30—\$150 plus plugs and/or parts

\$290 to \$350, plus parts

O/B \$165; Volvo \$1/O \$210; Mercruiser I/O \$310

\$200 to \$325, plus parts

\$35 plus battery

\$165 per hour per technician



Certified MerCruiser Dealer in Service and Warranty Work